

OFFICE OF THE DY. EXECUTIVE ENGINEER PANCHAYAT RAJ  
SUB-DIVISION, SIRICILLA.

BUILDING SAFETY CERTIFICATE

This is to certify that on inspection the GI sheet roofed structure in which the  
Kendriya Vidyalaya at Subhash Nagar in Sircilla , Rajanna Sircilla District is functioning is  
In safe condition to run the school.

  
Asst. Executive Engineer  
PR Sub-Division, SIRICILLA  
P R Sub-division Sircilla

  
प्रचार्य / PRINCIPAL  
केंद्रीय विद्यालय / KENDRIYA VIDYALAYA  
सिरिसिल्ला / SIRICILLA  
जिला राजन्ना सिरिसिल्ला / Rajanna Sircilla Dist  
पिन / PIN: 505301